


Release Notes

6000 Series Paperless Graphic Recorder



Eurotherm®

Expertise in systems and solutions, services and support

Legal Information

All rights are strictly reserved. No part of this document may be reproduced, modified, or transmitted in any form by any means, nor may it be stored in a retrieval system other than for the purpose to act as an aid in operating the equipment to which the document relates, without prior written permission of Eurotherm by Schneider Electric.

Eurotherm, the Eurotherm by Schneider Electric logo, Chessell, EurothermSuite, Mini8, Eycon, EPower, EPack nanodac, piccolo, versadac, Foxboro, and Wonderware are trademarks of Schneider Electric, its subsidiaries and affiliates. All other brands may be trademarks of their respective owners.

Eurotherm Limited pursues a policy of continuous development and product improvement. The specifications in this document may therefore be changed without notice. The information in this document is given in good faith, but is intended for guidance only. Eurotherm Limited will accept no responsibility for any losses arising from errors in this document.

Contents

- 1 Changes 4
 - 1.1 Changes in version 5.11 4
 - 1.2 Changes in version 5.10 4
 - 1.3 Changes in version 5.9.1 5
 - 1.4 Changes in version 5.9.0 5
 - 1.5 Changes in version 5.8.6 5
 - 1.6 Changes in version 5.8.5 6
 - 1.7 Changes in version 5.8.4 6
 - 1.8 Changes in version 5.8.3 6
 - 1.9 Changes in version 5.8.2 7

1 Changes

1.1 Changes in version 5.11

Release Date: May 2022

New Features:
None Identified.

Security Updates:
None Identified.

Items Resolved:

Ticket No	Summary
EXT-5769	SFTP filename limited to 64 characters, unable to handle long UHH filenames.
EXT-5797	C-Edit message when copying a math channel to another math channel
EXT-5967	Updated TLS version from V1.0 to V1.2 to allow use of Active Directory service hosted on Windows Server 2016 or 2019

1.2 Changes in version 5.10

Release Date: December 2021

New Features:
Updated to support AMS2750F and added 32-bit register support for EtherNet/IP option.

Security Updates:
None in this release

Items Resolved:

Ticket No	Summary
EXT-5594	Clock reverting to previous value if power cycled with a compact flash card fitted
EXT-5584, EXT-5628, EXT-5586, EXT-5350, DM-3906, DM-3907	Product entering diagnostic mode and year changing to 1999.
EXT-5608	Inability to establish a connection from Bridge if using SFTP and DNS features

1.3 Changes in version 5.9.1

Release Date: January 2021

New Features:

Maintenance release only

Security Updates:

Ticket	Summary
DM-3895	Security vulnerability with EtherNet/IP, for further information refer to https://nvd.nist.gov/vuln/detail/CVE-2020-25159

Items Resolved:

Ticket	Summary
DM-3848	"File not found" notification on a 6180XIO
DM-3850	Active Directory configuration parameters not being visible when creating a configuration for a 6100/6180XIO using C-Edit

1.4 Changes in version 5.9.0

Release Date: October 2020

New Features:

Maintenance release only

Security Updates:

None in this release

Items Resolved:

Ticket	Summary
DM-3892	Inability to establish a remote connection with a 6100E running V5.8.5 product firmware

1.5 Changes in version 5.8.6

Release Date: August 2020

New Features:

Maintenance release only

Security Updates:

None in this release

Items Resolved:

Ticket	Summary
DM-3887	Unable to connect to recorder - Target machine actively refused it
DM-3888	Security Manager downloads PW length of 10 digits, instrument shows 8
DM-3889	Inability to load a configuration file if the Engineer user account is disabled

1.6 Changes in version 5.8.5

Release Date: April 2020

New Features:

Maintenance release only

Security Updates:

None in this release

Items Resolved:

Ticket	Summary
#18072	LDAP security now enabled by default
#18074	Bridge network notification message is now non-editable
#18142	Allow 6000 diagnostic USB memory stick to disable California Law (SB327) in local HMI

1.7 Changes in version 5.8.4

Release Date: February 2020

New Features:

Maintenance Release only

Security Updates:

None in this release

Items Resolved:

Ticket	Summary
#18127	Upgrading via Bridge from local PC
#18128	Corrected Spanish translation for "SFTP enabled"
#18129	Updated French keyboard (alphabet 2)
#18133	Inability to establish a connection from Eyris when using Bridge V5.8.2

1.8 Changes in version 5.8.3

Release Date: August 2019

New Features:

Maintenance Release only

Security Updates:

None in this release

Items Resolved:

Ticket	Summary
#18117	Blocked HDI port

1.9 Changes in version 5.8.2

Release Date: July 2019

New Features:

SFTP support added

Security Updates:

None in this release

Items Resolved:

Ticket	Summary
#18112	Prevented device restart when user list opened whilst Security Manager is deploying updates